



A WILDFIRE PRO SHOP COMPANY

FIREPROSHOP
889 TAHOE BLVD., UNIT A
INCLINE VILLAGE, NV 89451
909-519-5470
FIREPROSHOP.COM

FOR BUILDERS & FRAMING CONTRACTORS

Three risk reductions for wood-framed construction.

Wood is renewable and grown across North America. The case for framing with it holds up better when both exposures below are documented and handled — while the framing is still open.

EXPOSURE 01 · MOISTURE

Water trapped under the plates

Once the walls are up and the drywall is on, the underside of the plate cannot be reached again.

EXPOSURE 02 · FIRE

Framed, but not yet defended

No sprinklers, no gypsum, a full load of exposed lumber. Cheyenne lost a four-story apartment on May 26. Denver lost one on January 2.

THREE LAYERS, EACH WITH A STANDARD BEHIND IT



01 — DRJ TER 2504-101

Class A lumber

Treated at the mill, arriving code-evaluated.



02 — ASTM E84 EXTENDED

Job-site fire defense

Sprayed as the walls go vertical. You keep your framer; we train them.



03 — ASTM G21

SNAP-PLATE MOLD DEFENDER™

Rolled on the snapped lines before the walls stand.

DRJ TER 2504-101

ASTM E84 · CLASS A

ASTM G21

CSI 06 05 73

**Fifteen minutes with Steve Conboy,
a framer who builds the chemistry.**

NO COST
TO GET NUMBERS

STEVE CONBOY · 909-519-5470
SALES@FIREPROSHOP.COM
FIREPROSHOP.COM